

Commission Memo

Prepared by: Michael McElwee
Date: July 9, 2019
Re: SBE Contract



The Port has retained Stafford Bandlow Engineering (SBE) on several occasions in the last few years to carry various out engineering tasks associated with the Hood River Bridge Lift Span. SBE has provided excellent services to the Port and has been instrumental in restoration of the fully functionality and safe operations of the lift span.

Now SBE has entered into an agreement to merge with Wiss, Janney, Elstner Associates (WJE), a leading global firm of engineers, architects, and materials scientists specializing in infrastructure projects. Due to this merger, SBE is seeking the Port's consent to the assignment of our only current contract, the design and engineering of the new span drive motors and skew system. The only significant remaining work on this contract is delivery of the as-built drawings for the recently completed work.

The assignment contract is attached.

RECOMMENDATION: Authorize Consent to Assignment of Contract with Stafford Bandlow Engineering subject to legal counsel review.

This page intentionally left blank.



STAFFORD BANDLOW ENGINEERING

June 28, 2019

Mr. Michael McElwee
Executive Director
Port of Hood River
1000 E. Port Maria Drive
Hood River, OR 97031

Dear Mr. McElwee,

We are excited to share some very important news regarding Stafford Bandlow Engineering (SBE). We have entered into an agreement to have our professionals join with Wiss, Janney, Elstner Associates (WJE) on July 1, 2019. WJE is a leading global firm of engineers, architects, and materials scientists specializing in solving problems in the built world.

As part of one of the world's premier problem-solving firms, we can now offer you a broad range of engineering, architectural, laboratory, design, and forensics services from WJE's twenty-eight offices around the world. This immediately expands the breadth of services our professionals can offer to better meet your needs.

While this may be the most significant change in our long history, we assure you that it will not be one that disrupts our service to you. Your existing contacts and relationships at SBE will not change. In order to transfer your agreement from Stafford Bandlow Engineering to Wiss, Janney, Elstner Associates, please sign the attached document and send it back to Andrew Katz (akatz@sbengineering.net) at Stafford Bandlow Engineering by July 15, 2019.

Please give me a call or send me a note if you have any questions or would like to discuss in more detail. We look forward to a new and exciting future as Stafford Bandlow Engineering, a division of WJE.

Sincerely,

Paul Bandlow
Principal

This page intentionally left blank.

SBE Job Number: SB796D

SBE Project Name: ElecDriveDesign

Client: Port of Hood River

CONSENT TO
ASSIGNMENT OF CONTRACT

Stafford Bandlow Engineering (SBE) entered into an agreement with Port of Hood River on January 29, 2018 (the "contract"). SBE wishes to assign all rights and delegate all duties remaining on that contract to Wiss, Janney, Elstner Associates, Inc. (WJE) effective July 1, 2019. Port of Hood River agrees to that assignment and delegation.

Port of Hood River

Design and Engineering of a New Skew System for Hood River Interstate Bridge Lift Span

By: _____

Name: _____

Title: _____

Date: _____

Please return this signed document to Andrew Katz (akatz@sbengineering.net) at Stafford Bandlow Engineering by July 15, 2019.



Form W-9
Request for Taxpayer Identification Number and Certification

Give Form to the requester. Do not send to the IRS.

Go to www.irs.gov/FormW9 for instructions and the latest information.

1 Name (as shown on your income tax return). Name is required on this line; do not leave this line blank.
Wiss, Janney, Elstner Associates, Inc.

2 Business name/disregarded entity name, if different from above

3 Check appropriate box for federal tax classification of the person whose name is entered on line 1. Check only **one** of the following seven boxes.

Individual/sole proprietor or single-member LLC
 C Corporation
 S Corporation
 Partnership
 Trust/estate
 Limited liability company. Enter the tax classification (C=C corporation, S=S corporation, P=Partnership) ▶ _____
Note: Check the appropriate box in the line above for the tax classification of the single-member owner. Do not check LLC if the LLC is classified as a single-member LLC that is disregarded from the owner unless the owner of the LLC is another LLC that is **not** disregarded from the owner for U.S. federal tax purposes. Otherwise, a single-member LLC that is disregarded from the owner should check the appropriate box for the tax classification of its owner.
 Other (see instructions) ▶ _____

4 Exemptions (codes apply only to certain entities; not individuals; see instructions on page 3).
 Exempt payee code (if any) **5**
 Exemption from FATCA reporting code (if any) _____
 (Apply to accounts rendered within the U.S.)

5 Address (number, street, and apt. or suite no.) See instructions.
330 Pfingston Road

6 City, state, and ZIP code
Northbrook, IL 60062

7 List account number(s) here (optional)

Requester's name and address (optional)

Part I Taxpayer Identification Number (TIN)

Enter your TIN in the appropriate box. The TIN provided must match the name given on line 1 to avoid backup withholding. For individuals, this is generally your social security number (SSN). However, for a resident alien, sole proprietor, or disregarded entity, see the instructions for Part I, later. For other entities, it is your employer identification number (EIN). If you do not have a number, see *How to get a TIN*, later.

Note: If the account is in more than one name, see the instructions for line 1. Also see *What Name and Number To Give the Requestor* for guidelines on whose number to enter.

Social security number
 [] - [] - []

OR
 Employer identification number
 3 6 - 2 7 5 7 9 5 6

Part II Certification

Under penalties of perjury, I certify that:

- The number shown on this form is my correct taxpayer identification number (or I am waiting for a number to be issued to me); and
- I am not subject to backup withholding because: (a) I am exempt from backup withholding, or (b) I have not been notified by the Internal Revenue Service (IRS) that I am subject to backup withholding as a result of a failure to report all interest or dividends, or (c) the IRS has notified me that I am no longer subject to backup withholding; and
- I am a U.S. citizen or other U.S. person (defined below); and
- The FATCA code(s) entered on this form (if any) indicating that I am exempt from FATCA reporting is correct.

Certification instructions. You must cross out item 2 above if you have been notified by the IRS that you are currently subject to backup withholding because you have failed to report all interest and dividends on your tax return. For real estate transactions, item 2 does not apply. For mortgage interest paid, acquisition or abandonment of secured property, cancellation of debt, contributions to an individual retirement arrangement (IRA), and generally, payments other than interest and dividends, you are not required to sign the certification, but you must provide your correct TIN. See the instructions for Part II, later.

Sign Here Signature of U.S. person ▶ *Maria Kaschuba* Date ▶ *5-9-19*

General Instructions

Section references are to the Internal Revenue Code unless otherwise noted.

Future developments. For the latest information about developments related to Form W-9 and its instructions, such as legislation enacted after they were published, go to www.irs.gov/FormW9.

Purpose of Form

An individual or entity (Form W-9 requester) who is required to file an information return with the IRS must obtain your correct taxpayer identification number (TIN) which may be your social security number (SSN), individual taxpayer identification number (ITIN), adoption taxpayer identification number (ATIN), or employer identification number (EIN), to report on an information return the amount paid to you, or other amount reportable on an information return. Examples of information returns include, but are not limited to, the following:

- Form 1099-INT (interest earned or paid)
- Form 1099-DIV (dividends, including those from stocks or mutual funds)
- Form 1099-MISC (various types of income, prizes, awards, or gross proceeds)
- Form 1099-B (stock or mutual fund sales and certain other transactions by brokers)
- Form 1099-S (proceeds from real estate transactions)
- Form 1099-K (merchant card and third party network transactions)
- Form 1098 (home mortgage interest), 1098-E (student loan interest), 1098-T (tuition)
- Form 1099-C (canceled debt)
- Form 1099-A (acquisition or abandonment of secured property)

Use Form W-9 only if you are a U.S. person (including a resident alien), to provide your correct TIN.

If you do not return Form W-9 to the requester with a TIN, you might be subject to backup withholding. See *What is backup withholding*, later.



Commission Memo

Prepared by: Michael McElwee
Date: July 9, 2019
Re: Bridge Approach Ramps Test Report



Concrete testing of the WA and OR approach ramps was carried out by HRD Engineering on May 15th. Mark Libby, P.E., the lead bridge engineer will attend the Commission meeting to discuss the test results and his recommendations.

RECOMMENDATION: Informational.

This page intentionally left blank.



Memo

Date: Friday, June 28, 2019

Project: Hood River – White Salmon Bridge

To: Michael McElwee, Executive Director
John Mann, Facilities Manager

From: Mark Libby, PE
Kurt Schweitzer, PE

Subject: **WA and OR Approach Spans Bridge Deck Inspection**

Background

The 2018-19 Task Order 08 included a review of the condition of the concrete approach span decks and joints and the need for deck overlay and joint rehabilitation.

The 2018 Routine Bridge Inspection Report lists a bridge deck condition rating of 5 (fair). The report notes transverse cracks in Spans D and E of the Oregon approach and spans 20 through 27 of the Washington approach, diagonal hairline cracks in the ends of the deck near the abutment with minor leaching, and some rutting in the wearing surface of the Washington approach spans with polished aggregate.

Based on comments from the Port about the condition of the overlay on the Washington approach spans, a brief walk of the deck was performed during a site visit in January 2019. The existing polymer overlay is worn through in multiple locations, several small potholes with exposed rebar are present and other areas of cracking indicate more are forming. Sample photos of the Washington approach spans deck condition are provided in *Attachment C - Deck Walk Photos*.

Based on the findings of similar inspection and chloride testing of deck cores at Bridge of the Gods that HDR conducted, chloride testing of deck cores in the Washington approach spans was recommended. The Washington Department of Transportation (WSDOT) uses rock salt on SR-14 to aid with icy conditions in winter months and salts are tracked on to the bridge approach spans.

With nighttime closures of the bridge for the 2019 Miscellaneous Truss and Steel Repairs project, the deck inspection work was targeted to occur during one of the nighttime closures.

We set our initial coring plan to collect four cores in the southbound (SB) lane (toward Oregon) and one core in the northbound (NB) lane (toward Washington).

Field Inspection


On May 15th, 2019 HDR staff performed the bridge deck inspection of the reinforced concrete deck on the Washington and Oregon approach spans of the Hood River - White Salmon Bridge. The inspection consisted of chain-dragging the deck to detect delaminations and collecting

concrete core samples for chloride testing. American Concrete Company performed the core-drilling of the deck. The work was performed during a nighttime bridge closure for another project and Port staff patched the core holes along with several pot holes in the deck.

Deck Coring

According to the 1951 plans, the Washington approach deck is 6 inches thick with 1.5 inches of clear cover to the top transverse reinforcement, No. 4 bars at 9 inches, plus No. 4 “truss” bars at 9 inches (Figure 1). The top longitudinal reinforcement is No. 4 bars at about 2-foot centers. The Oregon approach deck is 5.25 inches thick with 1.5 inches of clear cover to the top transverse reinforcement, No. 4 bars at 5.5 inches. The top longitudinal reinforcement is No. 4 bars at 18 inches. The desired core size for chloride testing is 4 inches in diameter with a depth at least 2 inches below the range for testing; in this case, 4.5-inch deep cores. Deck cores were only taken on the Washington approach.

Figure 1. Reinforced Deck Section



At each core hole ground penetrating radar scanning was used to locate the deck reinforcement. A vacuum was used to collect the water that keeps the coring bit cool then the core was broken free by tapping a screwdriver into the perimeter cut (Figure 2). The core was then photographed and placed into a sealed bag (Figure 3). Photographs were also taken of the hole (Figure 4) to evaluate concrete condition, and then the hole was patched. The core samples were delivered to the Oregon Department of Transportation (ODOT) laboratory facility in Salem, Oregon for testing. The core locations are shown on *Attachment A - Core and Delamination Location Plan*.

Figure 2. Core Drilling Apparatus



Figure 3. Core No. 4



Figure 4. Core No. 4 Hole



Deck Chain Drag

One of the best ways of detecting delaminated concrete on a flat surface is to drag a chain back and forth across the surface. The hollow-sounding ring of delaminated concrete is readily detectable. When delaminated areas were located the area was outlined with spray paint and the area and location were measured for mapping (Figure 5). The chain drag inspection covered the entire deck of the Washington and Oregon concrete approach spans. The areas of

delamination are shown on *Attachment A - Core and Delamination Location Plan*. Multiple locations of exposed deck rebar were observed during the deck inspection, with broken and corroded bars present.

Figure 5. Chain Drag Equipment



Deck Joints

The bridge deck joints in the concrete approach spans were not inspected closely during the deck inspection due to the nighttime conditions. A cursory observation was made of the Washington approach spans during the deck walk in January as well as a review of the inspection reports. The joint at Bent 28, Washington abutment, is in poor condition due to cracked and spalling concrete on the bridge side of the joint. The intermediate bent joints are generally in satisfactory condition. These joints consist of 0.5-inch joint filler between concrete diaphragms with an asphaltic sealer filled at the deck surface. The steel angle header at Bent 20, interface with the metal grid deck, has a 7-inch long section that is broken out in the SB lane. The inspection notes also indicate a vertical misalignment of 1-1/2-inch between the grid deck and the steel header (*Attachment C - Deck Walk Photos*).

The ODOT inspection notes indicate that the strip seal at Oregon Abutment E has lost adhesion and is leaking.

Laboratory Results


Deck Core Samples

Five core samples were tested in accordance with AASHTO T-260 (Chloride Content) test criteria. Each core is sliced into 0.5-inch-thick sections from the surface down. Each 0.5-inch slice is tested and the chloride content is reported as a percentage of the sample. Ideally five test samples would be obtained from a 4-inch x 4.5-inch core, however due to the large aggregate encountered the cores broke in a fashion that did not allow the lab to get five samples. Three of the cores only allowed for three samples while the other two allowed for four samples. The laboratory test results are shown in *Attachment B - Chloride Testing Results*,

which includes the raw lab report and graphical plots of these results. The graphical plot shows the chloride content at the mid-depth of each 0.5-inch sample, the assumed depth to reinforcement, and the corrosion threshold (Figure 6). The corrosion threshold is based on an industry accepted value of 0.04 percent or approximately 1.5 pounds of chloride per cubic yard of concrete. When this concentration of chloride reaches the depth of reinforcement, a corrosive condition is considered to exist. When the plotted curve connecting the test points is above the corrosion threshold at the location of the reinforcement, then active corrosion is occurring.

Figure 6. Core No. 3 Profile

Hood River - White Salmon Bridge		Field Test Data			
Sample #: 3	Depth, in	0.25	0.75	1.25	1.75
Date: 5/15/2019	Chloride Concentration	0.108	0.188	0.155	0.162



Core No. 3 (Figure 6) is notably the worst sample with all four of the sections testing well above the corrosion threshold. Cores No. 2 and 4, are the next worse with all of the testable sections well above the corrosion threshold. While cores No. 2 and 4 did not have a test sample below the reinforcement depth, the chloride level would not be expected to suddenly drop below the corrosion threshold. All sections of core No. 5, which is the only core taken in the NB lane, are also above the corrosion threshold. All sections of core No. 1, which was taken the farthest away from the centerline in the SB lane and closest to the Washington abutment, are below the corrosion threshold.

Cores No. 1 and 3 are in the approximate wheel paths for the SB lane while cores Nos. 2 and 4 are in the middle of the SB lane. Core No. 5 is in the inside wheel path of the NB lane.

Conclusions and Recommendations

The results of core No. 1 is unexpected as this location would presumably have the highest chloride concentrations, being closest to source of salt (SR-14). Core No. 5 results also indicate that the high chloride content is not restricted to the SB lane. However, these tests are individual spot locations, and if five more cores were tested, five different concentrations could result. What is more indicative of an active corrosion condition is the high level of chloride in cores No. 2 through 5 (2-to-4 times the corrosion threshold) and the high frequency of delaminations

in the SB lane of the Washington approach. As corrosion occurs, the steel volume expands and eventually causes a crack in the concrete. The impact of traffic in these areas further separates the concrete, eventually leading to failure and potholes. These cracks near the surface of the reinforcement are what give the hollow-sounding ring from the chain drag.

The concentration of delaminations in the NB lane of Spans 23-24 is also unexpected as these spans are within a supposed superelevated section, such that stormwater run-off is draining toward the SB lane. In discussions with John Mann, Facilities Manager, this section of the roadway routinely ponds water. This information helps explain the presence and concentration of delaminations in this area. It should be noted that while high chloride content is a leading cause of reinforcement corrosion, it is not the only cause of corrosion and deck delaminations.

The high chloride content in Core Nos. 2 through 5 and the high frequency of deck delaminations are good indications of an active corrosion condition in the deck reinforcement. This active condition will likely continue and result in additional deck delaminations and potholes in the future unless the condition is mitigated.

For the Oregon approach, Spans SD and SE have a high concentration of delaminations in the NB lane and only a few delaminations in the SB lane. The high level of delaminations in the NB lane may be indicative of vehicles tracking salts used around the toll booth onto the bridge.

The polymer overlay on both approach sections is worn through in much of the wheel paths and no longer providing much protection to the deck. Installing a new overlay on top of the deck in its current condition is not recommended due to the findings of high chloride content. The concern is that the level of chlorides trapped beneath the overlay will continue the corrosion of reinforcement, causing continued delamination and spalling of concrete and the overlay.

Washington approach Spans 20 to Span 22 are in more moderate condition with only a few delaminations, but no cores were tested in these spans. It is possible that the majority of salt brine being carried onto the bridge from SR-14 is deposited before getting to Span 22. Similarly the SB lane of Oregon approach Spans SD and SE are in more moderate condition than the NB lane.

For long term solutions, the chloride contaminated concrete needs to be removed. Short of a full deck replacement, this consists of removing the top 2.0 to 2.5 inches of concrete and replacing with a structural concrete overlay. This depth of removal gets at or below the top mat of reinforcement. Typically, when partial depth repairs in a bridge deck extend below mid-depth of reinforcement, removal needs to extend at least 0.5-inch beneath the reinforcement. This potentially involves a minimum of half of the deck in Spans 23 through 27. The cost and the impacts to traffic for this will be significant as this lane may be out of service for several weeks.

Before proposing a recommended solution additional information is warranted. We recommend taking additional cores in both the Oregon and Washington concrete approach span decks to better define the limits of chloride contamination. We recommend two additional cores in the Oregon spans, one each in NB lane of Spans SD and SE, and four additional cores in the Washington spans; NB lane of Span 23, 24, and 26, and the SB lane of Span 23.




Due to the limited samples obtained from the original set of cores we will attempt to get a slightly deeper core. This will likely not be possible in the Oregon spans due to the thinner deck and may be limited in Washington spans as well if bottom mat reinforcement is encountered.

The Capital/Maintenance Plan currently has Phase 1 seismic retrofit for Oregon approach spans in 2021-2022 and Washington approach spans in 2023-2024. Oregon approach span replacement is shown in 2030-2031 and Washington approach span replacement in 2034-2036. Consideration should be given to how this new information impacts those schedules and how projects may be combined or sequenced.



Attachment A - Core and Delamination Location Plan


This page intentionally left blank.



Core and Delamination Location Plan - Washington Approach

NTS


Total # of Delaminated Areas = 77 (~152 sq-ft)



Core and Delamination Location Plan - Oregon Approach

NTS

Total # of Delaminated Areas = 26 (~104 sq-ft)



Washington Approach Delminations

Hood River - White Salmon Bridge
Deck Delamination Locations - Washington Approach
SB Lane, Going South

Distance From Bent 28 (ft)	WxL (in)	Distance from CL, West (in)
7	17x18	60
13	14x12	15
14	22x22	32
15	16x16	84
17	16x18	16
28	16x16	16
30	9x40	8
37	96x6	43
38	13x20	68
39	17x24	30
41	21x30	10
41	23x30	79
47	14x23	46
49	34x47	15
50	16x27	63
50	28x32	85
54	19x55	58
60	29x16	14
61	27x53	52
63	16x16	11
67	24x24	19
67	17x45	57
72	16x20	28
75	20x13	24
75	16x40	56
87	22x20	49
90	16x32	6
103	40x58	8
107	16x13	112
118	30x18	51
120	44x40	22
133	26x25	28
135	14x15	121
136	18x18	41
142	169x16	117
145	16x18	112
157	15x23	45
159	25x22	22
168	19x18	96
169	24x24	35
171	23x23	12
195	108x54	9
199	26x27	36
213	28x22	124
233	23x16	39
234	40x23	85
234	18x28	12
270	15x12	125
273	18x19	34
296	12x22	92
303	14x14	77
303	16x20	16

Total Delaminated Area = 95.0 ft²
of Delaminated Areas = 52

Hood River - White Salmon Bridge
Deck Delamination Locations - Washington Approach
NB Lane, Going South

Distance From Bent 28 (ft)	WxL (in)	Distance from CL, East (in)
33	15x30	120
87	16x12	36
117	15x15	40
118	15x46	0
118	15x15	43
118	15x15	100
119	14x14	63
131	12x14	6
132	11x12	23
135	17x17	51
141	18x25	66
152	11x11	48
156	16x21	70
157	21x20	32
158	12x16	0
173	13x15	22
183	16x17	35
190	14x16	116
194	24x19	44
232	19x13	44
233	18x16	116
234	28x28	59
270	26x30	53
302	21x21	106
310	20x12	108

Total Delaminated Area = 57.2 ft²
of Delaminated Areas = 25

Oregon Approach Delminations

Hood River - White Salmon Bridge
Deck Delamination Locations - Oregon Approach
SB Lane, Going South

Distance From Bent 1 (ft)	WxL (in)	Distance from CL, West (in)
22	15x36	8
39	32x29	13
39	29x28	66
52	24x29	9

Total Delaminated Area = 20.7 ft²
of Delaminated Areas = 4

Hood River - White Salmon Bridge
Deck Delamination Locations - Oregon Approach
NB Lane, Going South

Distance From Bent 1 (ft)	WxL (in)	Distance from CL, East (in)
0	22x18	10
2	21x14	78
6	16x15	17
12	14x21	74
13	25x28	16
17	21x19	10
19	17x13	20
20	20x17	78
29	13x16	0
36	18x18	21
38	18x30	89
39	23x19	10
42	15x18	76
50	19x21	72
60	30x21	16
62	24x24	16
65	27x29	12
65	22x38	78
71	22x19	76
72	30x23	11
74	26x63	73
75	34x38	12

Total Delaminated Area = 82.8 ft²
of Delaminated Areas = 22

Core Locations

Core #	Distance from Bent 28, South (ft)	Lane	Distance from CL, West (in)	Distance from CL, East (in)
1	20.0	SB	134	-
2	48.0	SB	98	-
3	96.8	SB	37	-
4	127.2	SB	90	-
5	27.0	NB	-	47




Attachment B - Chloride Testing Results




Project: POHR T08	Computed: KFS	Date: 5/28/2019
Subject: Hood River - White Salmon Bridge Deck Insp	Checked: MAL	Date: 6/21/2019
Task: Chloride Sample Testing Results	Page: of:	
Job #: 10134023	No:	

Hood River - White Salmon Bridge		Field Test Data		
Sample #: 1	Depth, in	0.25	0.75	1.25
Date: 5/15/2019	Chloride Concentration	0.015	0.005	0.006




Hood River - White Salmon Bridge		Field Test Data		
Sample #: 2	Depth, in	0.25	0.75	1.25
Date: 5/15/2019	Chloride Concentration	0.122	0.172	0.176






Project: POHR T08	Computed: KFS	Date: 5/28/2019
Subject: Hood River - White Salmon Bridge Deck Insp	Checked: MAL	Date: 6/21/2019
Task: Chloride Sample Testing Results	Page: of:	
Job #: 10134023	No:	

Hood River - White Salmon Bridge		Field Test Data			
Sample #: 3	Depth, in	0.25	0.75	1.25	1.75
Date: 5/15/2019	Chloride Concentration	0.108	0.188	0.155	0.162




Hood River - White Salmon Bridge		Field Test Data		
Sample #: 4	Depth, in	0.25	0.75	1.25
Date: 5/15/2019	Chloride Concentration	0.186	0.149	0.165





Project: POHR T08	Computed: KFS	Date: 5/28/2019
Subject: Hood River - White Salmon Bridge Deck Insp	Checked: MAL	Date: 6/21/2019
Task: Chloride Sample Testing Results	Page: of:	
Job #: 10134023	No:	

Hood River - White Salmon Bridge		Field Test Data			
Sample #: 5	Depth, in	0.25	0.75	1.25	1.75
Date: 5/15/2019	Chloride Concentration	0.073	0.087	0.099	0.088



OREGON DEPARTMENT OF TRANSPORTATION
MATERIALS LABORATORY
800 AIRPORT RD. SE SALEM, OR 97301-4792

Page 1
(503)986-
FAX(503)986 4096

Contract No.: PRIVATE	EA No.: PRIVATE TESTING; Lab No.:	19-001195
Project: PRIVATE TESTING - HOOD RIVER BRIDGE DECK MAINTENANCE	County:	Data Sheet No.: P7420 281
Highway:	Contractor: HDR ENGINEERING	FA No.:
Contract Manager: MARK LIBBY	Org Unit:	Mid Item No.:
Submitted By: MARK LIBBY	Org Unit:	Sample No.:
Material Source:	Sampled By:	Qty Represented:
Sampled At: BR06645	Received: 19/ 5/21	Tested: 19/ 5/22
Class/Type: Quality Control	Use:	Date Reported: 19/ 5/23

TEST REPORT: CONCRETE CHLORIDE - BRIDGE

Sample ID	% ClO	% Cement	% Chlor by Sample	% Chlor by Cement
1-1			0.015	
1-2			0.005	
1-3			0.006	
2-1			0.122	
2-2			0.172	
2-3			0.176	
3-1			0.108	
3-2			0.188	
3-3			0.155	
3-4			0.162	
4-1			0.186	
4-2			0.149	
4-3			0.165	
5-1			0.073	
5-2			0.087	
5-3			0.099	
5-4			0.088	

17@ 525X=\$ 52.
30@ 233X= 75.

TOTAL CHARGES: \$ 2794.00

REMARKS:
INFORMATION ONLY
Test method 233x is for the concrete core prep work.
*

KEVIN BROPHY - LABORATORY SERVICES MANAGER

REPORT SHALL NOT BE REPRODUCED, EXCEPT IN FULL, WITHOUT WRITTEN APPROVAL OF THIS LABORATORY.

Q: FILES : PROJ NO: MARK LIBBY , HDR ENGINEERING : * SUITE - CHEMISTRY
MARK LIBBY@HDRINT.COM



Attachment C - Deck Walk Photos



Joint at Washington Abutment (Bent 28).



Pothole in Span 26, Joint at Bent 27.



Worn overlay near Bent 25.



Pothole in Span 22, Joint at Bent 23.



Worn overlay near Bent 22.



Broken steel header at Bent 20.

This page intentionally left blank.